## Amendments to the Specification:

5

## Please amend the following paragraph beginning at page 2, line 5 as follows:

Therefore, the working efficiency is extremely low, and besides there was an anxiety that the mounting precision is lowered. Consequently, productivity (working efficiency) is low, and camera placement accuracy is poor.

## Please amend the following paragraph beginning at page 3, line 9 as follows:

With such a configuration, the camera module can be easily exchanged when the camera module is found to be defective, defective.